Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO1275Work Order Type: WeatherizationAudit Name: 14014SO1275

CLIENT INFORMATION

Client Name: 14014SO1275 Address: , Unit 1214

Client ID: 14014SO1275 Columbia, TN 38401

Alt. Client ID: Maury

CLIENT CONTACT INFORMATION

14014SO1275 Applicant/Person of ✓

Record

<u>AGENCY INFORMATION</u>

Agency: South Central Human Resource Agency Agency Phone: (931) 433-7182

Address: 1437 Winchester Highway Fax: (931) 438-0074

Fayetteville, TN 37334 *Email Address:*

Agency Contact: Ford, Duane Work Phone:

Cell Phone: (615) 308-7878

Email Address: Fordd@hughes.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Bricked home in good cond.

Client Name: 14014SO1275 Client ID: 14014SO1275 Alt. Client ID: Maury Work Order (Bid Form)

Work Order Name: 14014SO1275 Report Run On: 5/14/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 4

Measures

	Measure 1 Infiltration Redctn					Components				
2	2. Re-secur	attic access. re R19 to floor where uctwork and mastic re		/.						
				Estimated Actual						
# Material / L	abor De	escription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Miscellane Supplies	eous Inf	filtration Reduction	Each	1						
2 Labor	La	bor	Hour	4						
Other Detail										
				Measur	e Sub Total:			Sub Total:		
Comment						Inspected				
# Matarial/I					-			4 . 4 4		
	obor De	poorintion / Commont	Unito	Otty	Estimated		Otv	Actual	Total	
# Material / L 1 Insulation		escription / Comment	<i>Units</i> Fach	Qty	Estimated Unit Cost	d Total	Qty	Actual Unit Cost	Total	
1 Insulation	Dł Ali pro Ap foi Ma	HW Pipe Insulation I corners must be cut operly. Refer to opendix A- Standards Weatherization aterials and Southeast eld Guide.	<i>Units</i> Each	Qty 1			Qty		Total	
1 Insulation	Dł All pro Ap foi Ma Fie	HW Pipe Insulation corners must be cut pperly. Refer to ppendix A- Standards Weatherization aterials and Southeast					Qty		Total	
1 Insulation	Dł All pro Ap foi Ma Fie	HW Pipe Insulation I corners must be cut operly. Refer to opendix A- Standards Weatherization aterials and Southeast eld Guide.	Each	1			Qty		Total	
1 Insulation2 Labor	Dł All pro Ap foi Ma Fie	HW Pipe Insulation I corners must be cut operly. Refer to opendix A- Standards Weatherization aterials and Southeast eld Guide.	Each	1			Qty		Total	
1 Insulation2 Labor	Dł All pro Ap foi Ma Fie	HW Pipe Insulation I corners must be cut operly. Refer to opendix A- Standards Weatherization aterials and Southeast eld Guide.	Each	1			Qty		Total	
1 Insulation2 Labor	Dł All pro Ap foi Ma Fie	HW Pipe Insulation I corners must be cut operly. Refer to opendix A- Standards Weatherization aterials and Southeast eld Guide.	Each	1					Total	

Client Name: 14014SO1275 Client ID: 14014SO1275 Alt. Client ID: Maury

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: 14014SO1275 Version 8.5.0 Report Run On: 5/14/2010

Page 2 of 4

		Total (Act Oty Unit	Cost	Total
1		Total G			Total
1	Total:		Sub To	otal:	
	Total:		Sub To	otal:	
easure Sub	Total:		Sub To	otal:	
easure Sub	Total:		Sub To	otal:	
easure Sub T	Total:		Sub To	otal:	
easure Sub T	Total:		Sub To	otal:	
		H&S	Act		spected
		Total G			Total
1					
1					
easure Sub			Sub To		
(Es Qty Unit	Estimated Qty Unit Cost	Qty Unit Cost Total G	Estimated Act Qty Unit Cost Total Qty Unit	Estimated Actual Qty Unit Cost Total Qty Unit Cost

1	Measure 5	-	or Barrier Needed ement/Crawlspace)			Componen	ts H&S		1	Inspected	
C	omment										
					Estimated			Actual			
#	Material / Lab	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and S Items	Safety	Basement / crawlspace vapor barrier	Each	1						
2	Labor		Labor	Hour	1						
(Other Detail] [
L] []			
					Measur	e Sub Total:] .	Sub Total:		
	Field Notes:					-					
				Work Or	der Gra	and Total:		Gran	d Total:		